Annexure D

BUILDING SAFETY CERTIFICATE

NO. 2078 BSC 202526

DATED:31/07/2025

It is certified that <u>HOLY ANGEL SCHOOL</u> (name of the building or premises) at <u>VILL DEVLI, P.O.</u>

<u>KIRTINAGAR, TEHRI GARHWAL, UTTARAKHAND</u> (address) is having block(s)/floors(s) as per details below:

Detail of block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. Of floor(s) in the block	GROUND+3					

The building is owned/occupied by <u>HOLY ANGEL SCHOOL</u> (name of the institution) have complied with the building safety requirements in accordance with national building code rules, and verified by the officers concerned of <u>P.W.D.</u>, <u>SRINAGAR GARHWAL</u> (name of department/govt.) On <u>03/07/2025</u> (date of inspection) in the presence of <u>Mr. AJAY PRAKASH JOSHI, PRINCIPAL, HOLY ANGEL SCHOOL</u> (name and address of the manager/secretary or his representative) and that the building/ premises is fit for occupancy for running school with effect from <u>30/07/2025</u> for a period of <u>2(TWO)</u> years in accordance with rule and subject to compliance of the specific conditions as appended.

- Capacity of classroom should be kept as per classroom size.
- 2. Building should be got inspected after any natural disaster in area.
- 3. Fire safety and other safety standards should be as per prevailing guidelines of Fire Department.
- 4. Certificate is valid for above indicated period under normal circumstances.
- 5. In case of any defect observation in building due to internal or external reasons, inspection from authorized engineer must be conducted immediately.

Issued on 30/07/2025 at 01:30 PM by ASSISTANT ENGINEER,PWD

 Strike out whichever is not applicable. In case of block is more than six use separate sheet for details.

Signature wit

Name:

Designation:

Name & Address Of Department/Office: PWD

MP. STINGS